



Start-Conditions :  
 $V_{in} \geq V_{in,min}$   
 Pin 11 and Pin 12 must be connected  
 with each other.  
 (Push Button function enable output)



Customer Connector



Pin No.	Pin Assignment
1	ground (110V)
2	to dead battery start loads
3	to 110VDC
4	n.c.
5	floating contact
6	indikation: K1 closed and operation
7	floating contact
8	indikation: K1 closed and operation
9	indikation: failure
10	floating contact
11	External push button
12	External push button

Wago-Order Number: Federleiste type KZF 5mm 721-112/026-000

Schutzvermerk nach DIN 34		Maßstab	Gewicht	Oberfläche		Werkstoff	Freimaßtoleranz DIN 2768m	
					Datum	Name	Bezeichnung	
				Bearb.	04.05.16	Feuring	400 NSB 750 M110	
				Gepr.	.	.	Pin Assignment	
				Norm	.	.	Artikelnummer	
Zust.		Änderung	Datum	Name	Ers. für:			Blatt 1
								Blätter 1

**Grau**  
 Elektronik  
 GmbH